Flash Report | Windstorm and Rainfall Damages to IDP Sites



Gwoza, Maiduguri, Jere, and Konduga LGA (Local Government Area)

06 June 2020

SUMMARY



89 Households





10 sites



149 Damaged shelters




30 Damaged toilets



With the onset of the rainy season in Nigeria's confict-affected northeastern State of Borno, varying degrees of damages are expected to infrastructures (self-made and constructed) in camps and camp-like settings. This is so because the rains are more often than not accompanied by very high winds and have been known to cause serious damage to properties.

On 5 May 2020, IOM's DTM program carried out an assessment to ascertain the level of damage sutained in camps and camp-like settings due to heavy windstorm and rainfall between 4th and 5th June 2020. Overall, 10 camps were affected in Gwoza, Maiduguri, Jere and Konduga LGAs.

Affected camps include: Camp D (Damara Arrival Center), Camp E in Gwoza LGA; Bakasi Camp, Doron Baga Camp, Eyn Can Center Camp in Maiduguri Metropolitan Council (MMC); Ahmed Grema Camp, Custom House, Musari Camp in Jere LGA and 250 Housing Estate (Dalori II), Federal Training Center Camp (Dalori I) in Konduga LGA.



The maps in this report are for illustration purposes only. The depiction and use of boundaries, geographic names, and related data shown on maps and included in this report are not warranted to be error free nor do they imply judgment on the legal status of any territory, or any endorsement or acceptance of such boundaries by IOM.

There is a major need of shelter, shelter repair kits, construction and cleaning of drainages as a preparedness measure in all camps, provision of basic NFI as well as reconstruction of damaged toilets and shower areas. No casualty was reported except in Bakasi Camp in Maiduguri where 2 individuals were injured.

Damages at IDP Sites between 4th and 5th June 2020

LGA	Site ID	Site Name	Number of Households	Number of Individuals	Number of Damaged shelters	Number of damaged toilets	Number of damaged showe points
Gwoza	BO_S240	Camp D (Damara Arrival Centre)	8	32	40	8	0
	BO_S246	Camp E	3	15	3	3	0
Gwoza Total			11	47	43	11	0
Jere	BO_S324	Ahmed Grema	35	165	35	0	0
	BO_S151	Custom House	0	0	0	5	0
	BO_S159	Musari Camp	5	12	5	0	0
Jere Total			40	177	40	5	0
Konduga	BO_S021	250 Housing Estate (Dalori 2)	0	0	0	1	0
	BO_S016	Federal Training Center Camp (Dalori I Camp)	10	32	38	0	0
Konduga Total			10	32	38	1	0
Maiduguri M. C.	BO_S010	Bakasi Camp	14	60	14	3	1
	BO_S318	Doron Baga Camp	14	49	14	0	0
	BO_S012	Eyn Can Centre Camp	0	0	0	10	4
Maiduguri M. C. Total			28	109	28	13	5
Grand Total			89	365	149	30	5

DATA SOURCE: IOM-DTM RAPID ASSESSMENT TEAM

"When quoting, paraphrasing, or in any other way using the information mentioned in this report, the source needs to be stated appropriately as follows: "Source: The International Organization for Migration [Month, Year], Displacement Tracking Matrix (DTM)"





