

## Flash Report | Windstorm and rainfall damages to IDP sites

IOM DTM Rapid Assessment



Maiduguri M.C, Konduga, Jalingo LGAs (Local Government Areas) of Borno and Taraba State

14 July 2021

## **SUMMARY**














379 Flooded/Damaged shelters

355 Flooded/Damaged toilets 187 Flooded/Damaged shower points

With the onset of the rainy season in Nigeria's conflict-affected northeastern state of Borno and Taraba, varying degrees of damages are expected to infrastructures (self-made and constructed) in camps and camp-like settings. Usually, heavy rainfalls are accompanied by strong winds causing serious damage to shelters of IDPs.

Between 08 and 14 July 2021, IOM's DTM program carried out assessments to ascertain the level of damage sustained in camps and camp-like settings due to heavy windstorms and rainfall. Overall, 2 collective settlement and 1 host community in Konduga and Maiduguri M.C LGAs in Borno State and 1 host community location in the LGA Jalingo of Taraba State were assessed. The worst-hit of the collective settlements assessed was 400 Housing Estate camp in Auno/Chabbol Ward of Konduga LGA where a heavy rainfall damaged 7 shelters. affecting an estimated 100 individuals.

On 10 July 2021, there was a heavy rainfall in Jalingo that flooded most areas in Mayo Goi river area in Mayo Goi ward. This incident caused the river to overflow it banks thereby flooding about 355 shelters and damaging properties of residents.



The maps in this report are for illustration purposes only. The depiction and use of boundaries, geographic names, and related data shown on maps and included in this report are no warranted to be error free nor do they imply judgment on the legal status of any territory, or any endorsement or acceptance of such boundaries by IOM


There is a major need of WASH, shelter repair kits and Shelter. As a preventive measure against flooding, most IDP sites need good drainage systems and the use of sand bags to channel the water flow.







Most Needed Assistance. FIG 1.1



Above are Pictures taken at some sites showing flooded areas.

## **Damages at IDP Sites**

State	LGA	Ward	Site Type	Site Name	Number Affected Household	Number of Affected Individuals	Male	Female	Number of Damaged Shelters
Borno	Konduga	Auno / Chabbol	Collective settlement	400 Housing Estate Gubio	17	100	44	56	7
Borno	Maiduguri M. C.	Maisandari	Collective settlement	Kuru Camp	9	49	20	29	9
Borno	Maiduguri M. C.	Maisandari	Host communities	SARE 1 Camp	8	41	15	26	8
Taraba	Jalingo	Mayo Goi	Host communities	Mayo Goi	355	1,775	821	954	355
<b>Grand Total</b>					389	1,965	900	1,065	379

DATA SOURCE: IOM-DTM RAPID ASSESSMENT TEAM

<sup>&</sup>quot;When quoting, paraphrasing, or in any other way using the information mentioned in this report, the source needs to be stated appropriately as follows: "Source: Displacement Tracking Matrix (DTM) of the International Organization for Migration (IOM), July 2021""



