

Flash Report | Windstorm and rainfall damages to IDP sites

IOM DTM Rapid Assessment

Maiduguri, Jere and Monguno LGAs (Local Government Areas) - Borno State



29 July 2021

SUMMARY













1,362 Damaged/Flooded shelters


23 Damaged toilets

17 Damaged shower points

With the onset of the rainy season in Nigeria's northeastern state of Borno, varying degrees of damages have been reported in camps and camp-like settings. Heavy rainfalls, accompanied by strong winds have caused serious damages to IDP shelters and camp infrastructures.

Between 22 and 28 July 2021, IOM's DTM programme carried out assessments to ascertain the level of damage sustained in camps and camp-like settings due to heavy windstorms and rainfall. Overall, 5 collective settlements, 1 transitional center and 6 camps in Maiduguri M.C, Jere and Monguno LGAs were assessed. The worst-hit of the assessed sites was Tausayi IDP Camp, a collective settlement in Bolori ii ward of Maiduguri M.C LGA, where a heavy rainstorm damaged 481 shelters, affecting an estimated 2,385 individuals.

In total, 1,362 shelters were either damaged or flooded by storms, leaving a total of 2,235 households in immediate need of shelter. There were no casualties reported as a result of the storms.



The maps in this report are for illustration purposes only. The depiction and use of boundaries, geographic names, and related data shown on maps and included in this report are not warranted to be error free nor do they imply judgment on the legal status of any territory, or any endorsement or acceptance of such boundaries by IOM


There is a major need of shelter, shelter repair kits and WASH assistance as most shelters need re-enforcement. As a preventive measure against flooding, most IDP sites need good drainage systems and the use of sand bags to channel the water flow.







Most Needed Assistance. FIG 1.1



Response

No assistance has been given on the date of publication.

Above is a Picture taken at the site showing the flooded areas.

Damages at IDP Sites

Above are Pictures taken at the site showing damaged shelters.

LGA	Ward	Site Type	Site Name	Number of Affected Household	Number of Affected Individuals	Male	Female	Number of Damaged Shelter	Number of Damaged Toilets	Number of Damaged showers
Jere	Dusuman	Camp	Bulamatari Camp	7	37	16	21	7	0	0
	Old maiduguri	Camp	Al-yakub	9	46	22	24	9	0	0
	Old maiduguri	Camp	Annur Camp	83	373	173	200	83	0	0
	Old maiduguri	Camp	Faria gidan block Camp	89	439	199	240	89	0	0
	Old maiduguri	Camp	Madinatu Camp	12	57	27	30	12	0	0
	Old maiduguri	Camp	Shuwari filling ball Camp	30	186	84	102	30	0	0
	Old maiduguri	Transitional centre	El-miskin Camp ii	455	1,635	753	882	455	0	0
			JERE TOTAL	685	2,773	1,274	1,499	685	0	0
Maiduguri m. c.	Bolori i	Collective settlement	Teachers village	223	688	282	406	177	16	10
	Bolori ii	Collective settlement	Tausayi idp Camp	421	2,385	1,025	1,360	481	7	7
	Maisandari	Collective settlement	Kuru Camp	18	89	37	52	18	0	0
			MAIDUGURI M.C TOTAL	662	3,162	1,344	1,818	676	23	17
Monguno	Monguno	Collective settlement	GGSS Camp	820	1,235	583	652	0	0	0
	Monguno	Collective settlement	NRC 1 & 2	68	264	131	133	1	0	0
			MONGUNO TOTAL	888	1,499	714	785	1	0	0
Grand Total				2,235	7,434	3,332	4,102	1,362	23	17

DATA SOURCE: IOM-DTM RAPID ASSESSMENT TEAM

"When quoting, paraphrasing, or in any other way using the information mentioned in this report, the source needs to be stated appropriately as follows: "Source: Displacement Tracking Matrix (DTM) of the International Organization for Migration (IOM), July 2021""

