

Flash Report | Windstorm and rainfall damages to IDP sites

IOM DTM Rapid Assessment

Maiduguri, Jere and Monguno LGAs (Local Government Areas) - Borno State



06 August 2021

SUMMARY













360 Damaged/Flooded shelters


No Damaged toilets

No Damaged shower points

With the onset of the rainy season in Nigeria's northeastern state of Borno, varying degrees of damages have been reported in camps and camp-like settings. Heavy rainfalls, accompanied by strong winds have caused serious damages to IDP shelters and camp infrastructures.

Between 29 July and 05 August 2021, IOM's DTM programme carried out assessments to ascertain the level of damage sustained in camps and camp-like settings due to heavy windstorms and rainfall. Overall, 3 collective settlements, 1 camp and 1 host community location in Maiduguri M.C LGA were assessed. The worst-hit of the assessed sites was Tausayi IDP Camp, a collective settlement in Bolori II ward of Maiduguri M.C LGA, where a heavy rainstorm damaged 111 shelters, affecting an estimated 556 individuals.

In total, 360 shelters were either damaged or flooded by storms, leaving a total of 360 households in immediate need of shelter. There were no casualties reported as a result of the storms. There is a major need of shelter repair kits, shelter, food and NFI assistance as most shelters need re-enforcement. As a preventive measure against flooding, most IDP sites need good drainage systems and the use of sand bags to channel the water flow.




The maps in this report are for illustration purposes only. The depiction and use of boundaries, geographic names, and related data shown on maps and included in this report are not warranted to be error free nor do they imply judgment on the legal status of any territory, or any endorsement or acceptance of such boundaries by IOM















Response

No assistance has been given on the date of publication.

Above are Pictures taken at the site showing damaged shelters and properties.

Above are Pictures taken at the site showing flooded areas shelters.

Damages at IDP Sites

LGA	Ward	Site Type	Site Name	Number of Affected Households	Number of Affected Individuals	Male	Female	Number of Damaged Shelter	Number of Damaged Toilets	Number of Damaged Showers
Maiduguri M. C.	Bolori ii	Collective settlement	Doron baga camp	101	355	140	215	101	0	0
	Bolori ii	Collective settlement	Tausayi idps camp	111	556	270	286	111	0	0
	Bulabulin	Camp	Biafra camp	103	518	229	289	103	0	0
	Maisandari	Collective settlement	Kuru camp	22	116	47	69	22	0	0
	Maisandari	Host communities	SARE 1 CAMP	23	124	48	76	23	0	0
Grand Total				360	1,669	734	935	360	0	0

DATA SOURCE: IOM-DTM RAPID ASSESSMENT TEAM

"When quoting, paraphrasing, or in any other way using the information mentioned in this report, the source needs to be stated appropriately as follows: "Source: Displacement Tracking Matrix (DTM) of the International Organization for Migration (IOM), August 2021""

